See Instructions on back of page 6.

Department of Toxic Substances Control Sacramento, California

UNIFORM HAZARDOUS WASTE MANIFEST	1. Generator's US E	45/1000	Manifest Docume	ent No.	2. Page 1		n the shaded areas ed by Federal law.
Senerator's Name and Mailing Address			Maries (Saries 1999)	NAME OF TAXABLE PARTY O	Manifest Document	Number 🚜 🧸	
ICLO LAKEULOO BUO LONG BEACH CA 90	65 FW 808			B. State	Generator's ID	A. H. A.	326014
Generator's Phone (562 62	7-3011				1HQ36	0 0 1	1/10 T
Transporter 1 Company Name		S US EPA ID Number			Transporter's ID	(計畫)	
ASBURY ENVIRONMENTAL SERVICES CADO282					NA STATE	310)000	3-3400
Transporter 2 Company Name		3. US EPA ID Number		, it. 10	Transporter's ID oorler's Phone		
9. Designated Facility Name and Site Address 10. US EPA ID Number DEMENNO KERDOON 2000 NORTH SLANDA STREET, CONFTON, CA 90222				G. State Focility's ID CAT080013352			
		ATOSO	01335		y's Phone (31	01537-7	100
US DOT Description (including Proper Ship	pping Name, Hazard Clas	s, and ID Number)		ontainers	13. Total	14. Unit	
" MON-RCRA HAZARDOUS			No.	Туре	Quantity		I. Waste Number State 135
(WATER, OIL)	No	Placard Rec	wired OO	rr	00150	G	EPA/Other NONE
b .							State
							EPA/Other
							State
					1111		PA/Other
d.							Stale
							EPA/Other
additional Descriptions for Materials Listed A	Above			K. Handl	ing Codes for Waste	s Listed Above	
APER 6				a.		b. 1	
are		NABRG #171		c.		d.	
Special Handling Instructions and Addition	al Information						001539
iloves 4 googles							LO)367-3408
GENERATOR'S CERTIFICATION: I hereby marked, and labeled, and are in all respec	declare that the contents of tts in proper condition for	this consignment are fu transport by highway o	lly and accurately desc according to applicable	ribed above e internation	by proper shipping n il and national gove	ame and are cl rnment regulat	assified, packed, ons.
If I am a large quantity generator, I certify practicable and that I have selected the prand the environment; OR, if I am a small available to me and that I can afford.	acticable method of freatr	nent storage or dispos	al currently available.	ta me which	minimizes the proce	at and future th	root to burne boulth
ted/Typed Name KEN WILSON		Signature	11/1/2	T/KI90	<i>3740</i>	Month.	Day 9 Yea
Transporter 1 Acknowledgement of Receipt		Signature	aul 4	Derke	•	Month	Day Yeo
Transporter 2 Acknowledgement of Receipt	of Materials				•		
		Signature		¥ 11.		Month	Day Yea
ted/Typed Name							
ed/Typed Name Discrepancy Indication Space							

DO NOT WRITE BELOW THIS LINE.

FACILITY

IN CASE OF EMERGENCY OR SPILL, CALL THE NATIONAL RESPONSE CENTER 1-800-424-8802: WITHIN CALIFORNIA, CALL 1-800-852-7550